



TL 9000 Informational Alert

1. Originating Working Group: Working Group: Oversight, AB/CB Sub-team Contact: contact@questforum.org	2. Alert Number: 21-005A
3. Documentation Affected: Qualification and Experience Requirements for TL 9000 Certification Body Auditors	4. Issue Date: 05 OCT 2021
5. Reason for Alert: To announce version 7.0 of the subject document.	
6. Description: This release added a new requirement in Section 5 Failure to Maintain Qualifications item 2 for TL 9000 Lead Auditor requalification: "If a TL 9000 lead auditor does not meet the criteria for leading TL 9000 audits (misses TIEA witness in the first year), s/he must be witnessed by a TIEA to requalify. All other requirements must continue to be met." Also added an example in Section 3: Qualification Requirements for TL 9000 Lead Auditors. There were no requirement changes in Section 3.	
7. Comments: Effective date September 16, 2021 To review the full document, it is posted at - TL 9000 Auditor Qualifications and Experience	